

SPOA7 / SPOA9 Lifts (Non Inbay Models)

Yes, the power unit can be installed on the driver's side of the lift (consult a Rotary Authorized Installer) but the preferred location is the passenger side.

The factory has located the power unit on the passenger side of the lift to reduce the steps required for the technician when positioning the adapters and raising the vehicle.

Typically, when placing a vehicle on the lift, the technician spots the left front wheel in the proper spotting dish position, as determined by the wheelbase. The technician then exits the vehicle and proceeds to locate each adapter according to the vehicle manufacturers recommended lift points, first on the driver's side, then on the passenger's side. By locating the power unit on the passenger side of the lift he is now ready to continue with the lifting procedures.

See SPOA7 / SPOA9 Operation Instructions for further details.

2 Post Inbay Models

On a 2 Post Inbay lift the power unit can be installed on either side side of the lift as long as the master control box is located on the same side as the power unit.